


GYMKANA CALIBRATION

TIP: Use included stylus with touch screen to ensure accurate selections


Follow the steps below




Select **SETUP**.




Select **CALIBRATIONS**.



Select **TRACER SETUP**.




Insert the calibration template as shown.
PRESS START.




Loosen the tracer knob, lower the **TRACER** and tighten the knob. **PRESS OK**




CALIBRATION, cont.



REMOVE the V037 CUTTER. PRESS OK




Install the T00 Calibration **TRACER** into the cutter spindle. Tighten the set screw and **CLOSE THE SHIELD**. PRESS OK




The **MACHINE** will **START** the setup process.


CALIBRATION, cont.



When prompted, loosen the tracer knob, **LIFT THE TRACER** and **MOVE IT TO THE RIGHT**. Close the shield. **PRESS OK**



PRESS OK.



Write down the X & Y values and **PRESS THE SAVE BUTTON**. **PRESS YES** to save the results. **PRESS THE BACK BUTTON** after checking their values (see next page).

CALIBRATION, cont.

IMPORTANT

Run the Tracer Setup process a second time and compare the X & Y values of this process with the previous set. The values should not change more than +/- 3.

EXAMPLE:


If during the first calibration process $X= 0$ and $Y= -4$.

In the second calibration process:


X must be between values -3 and +3

Y must be between values -7 and -1.



If the values are outside the +/- 3 variation run the calibration process a third time and compare the second set of numbers to the third. Press the **BACK** button.



Press **TRACER ADJUSTMENT**.




PRESS START.



REMOVE CALIBRATION TRACER T00 from the cutter spindle. PRESS OK



CALIBRATION, cont.



Install the **CUTTER V037**. PRESS **OK**




The machine will move the tracer over the jaw.



Loosen the tracer knob, lower the **TRACER**, tighten the **KNOB**. PRESS **OK**

CALIBRATION, cont.




PRESS OK and then **PRESS BACK**.



Press **JAW SETUP** and **SELECT U JAW**




Make note of the values of **X,Y,Z**.
PRESS START.



Completely remove the **CHIPS** from the **TRACER**, the **JAW** and the **KEY**.
PRESS OK.

CALIBRATION, cont.



PRESS OK.



PRESS SAVE.

IMPORTANT

Run the calibration a second time and compare the X, Y & Z values with the first set of numbers and make sure that they do not change more than +/- 3.

EXAMPLE:

If the first calibration values are X= -44, Y= -51 and Z= -28

In the second calibration values can be:

X must be between -47 and -41

Y must be between -54 and -48

Z must be between -31 and -25

If the values are outside the +/- 3 variation run the calibration process a third time and compare the second set of numbers to the third.