

# EEPROM XTRA. KIT APPLICATIONS

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>ABARTH</b>						
500	2007	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Grande Punto	2005	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>ACURA</b>						
CL	1996	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
CL	1998	2005	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Integra	1997	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Integra	1998	2005	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
MDX	2000	2007	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
MDX	2001	2008	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
NSX	1997	2006	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
RL	2001	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
RL	2002	2007	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
RSX	2002	2007	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
SLX	1999	2005	93c66 8pin, 512 Bytes	HD90U/HD90TK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
TL	1998	2001	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
TL	1999	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
<b>ALFA ROMEO</b>						
145	1995	2001	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
146	1995	2001	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
147	2000	2010	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
147	2000	2010	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
155	1995	1998	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
159	2005	2011	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
159	2005	2011	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
164	1995	1998	93c46 8pin, 128 Bytes	AR16U/AR16TK1	TK100	Philips® fixed code PH00 (33)
GT	2003	2010	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
GT	2003	2010	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
GTV	1995	1998	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
Mito	2008	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Spider	1995	1998	93c46 8pin, 128 Bytes	AR1505TK1	-	Philips® fixed code PH00 (33)
<b>APRILIA</b>						
Atlantic 500	2003	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
Dorsoduro	1996	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
Mana 850	1996	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
RSV1000	2004	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
Scarabeo 500	2003	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
Shiver	1996	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
SR 50	-	-	24c01, 8pin, 128 Bytes	ZAD18TK5	-	Temic® fixed code TM20 (12)
<b>AUDI</b>						
80	-	1996	93c46 8pin, 128 Bytes	V35U	TK100	Megamos® fixed code MG00 (13)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>AUDI</b>						
A4	1996	1998	93c46 8pin, 128 Bytes	V66U/V66TK/V66-KF	TK100/GKM	Megamos® fixed code MG00 (13)
A6	1995	1997	93c46 8pin, 128 Bytes	V35U/V66U/V66TK/V66-KF	TK100/GKM	Megamos® fixed code MG00 (13)
A8	-	2008	93c86(28000766), 8pin, 2048 Bytes	V35U	TK100	Philips® Crypto PH20 (46)
<b>BENTLEY</b>						
Flying Spur	-	2008	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
<b>BUICK</b>						
Regal	2012	-	Atmel 16K	-	-	Philips® Crypto PH20 (46)
<b>CHEVROLET</b>						
Aveo	2012	-	Atmel 16K	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Aveo	2006	2008	93c56 8pin, 256 Bytes	DAE48SU/DAE48STK	TKM	Megamos® Crypto MG10 (48)
Camaro	2010	2014	24c16 8pin, 2048 Bytes	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Camaro	2015	-	24C32	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Captiva	2006	2010	95040, 8pin, 512 Bytes	DAE47U/DAE47TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Cobalt	2006	2010	95040, 8pin, 512 Bytes	B106U/B106TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Cruze	-	2007	24c16 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
HHR	2006	2010	95040, 8pin, 512 Bytes	B106U/B106TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kalos	2006	2008	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Matiz	2005	-	93c56 8pin, 256 Bytes	DAE49U/DAE49TK	TKM/GKM	Megamos® Crypto MG10 (48)
Onyx	2012	-	Atmel 16K	-	-	Philips® Crypto PH20 (46)
Spark	2008	-	93c56 8pin, 256 Bytes	DAE49U/DAE49TK	TKM/GKM	Megamos® Crypto MG10 (48)
Tacuma	2000	-	93c56 8pin, 256 Bytes	DAE48SU/DAE48STK	TKM/GKM	Megamos® Crypto MG10 (48)
<b>CHRYSLER</b>						
300	2005	-	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
300	2005	-	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
300	2005	-	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Cirrus	1999	2000	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Cirrus	1999	2000	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Cirrus	1999	2000	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Concorde	1999	2004	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Concorde	1999	2004	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Concorde	1999	2004	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Crossfire	2004	-	24c02 8pin, 256 Bytes	-	-	Texas® Crypto TC04-64 (4D-64)
Crossfire	2004	-	Motorola MC68HC08AB16A, 64pin, 512 Bytes	-	-	Texas® Crypto TC04-64 (4D-64)
Crossfire	2004	-	Motorola MC68HC08AZ32, 64pin, 512 Bytes	-	-	Texas® Crypto TC04-64 (4D-64)
Intrepid	2001	-	Motorola MC68HC08AZ32, 64pin, 512 Bytes	-	-	Texas® Crypto TC04-64 (4D-64)
Neon	2000	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Neon	2000	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Neon	2000	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Pt Cruiser	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Pt Cruiser	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Pt Cruiser	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Sebring	2001	-	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Sebring	2001	-	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Sebring	2001	-	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>CHRYSLER</b>						
Sebring Coupe	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Sebring Coupe	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Sebring Coupe	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Stratus	1999	2000	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Stratus	1999	2000	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Stratus	1999	2000	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Town & Country	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Town & Country	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Voyager	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Voyager	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Voyager	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Ypsilon	1996	2003	Motorola MC68HC05E6, 28pin, 160 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Ypsilon	1996	2003	Motorola MC68HC08AZ32, 64pin, 512 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
<b>CITROËN</b>						
Berlingo	1998	2001	93c46 8pin, 128 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Berlingo	2008	-	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Elysee	2002	-	93c46 8pin, 128 Bytes	PG33U/PG33TK/PG33-KF	TK100/TK5	Philips® fixed code PH00 (33)
Evasion	1998	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Evasion	1998	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Evasion	1998	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumper	1996	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK/FT50ATK5	TK100/GKM	Megamos® fixed code MG00 (13)
Jumper	2006	2011	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Jumper	2006	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Jumper	2010	2012	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Jumper	2012	2015	95640	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Jumpy/Dispatch	1998	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumpy/Dispatch	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Jumpy/Dispatch	1998	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Nemo	2008	-	93c86(28000766), 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Relay	1996	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK/FT50ATK5	TK100/GKM	Megamos® fixed code MG00 (13)
Relay	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Relay	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Relay	2010	2015	95160, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Saxo	1996	2003	93c46 8pin, 128 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Synergie	1998	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Synergie	1998	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Synergie	1998	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xantia	1997	1999	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xantia	1998	1999	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xsara	1998	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Xsara	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
<b>DACIA</b>						
Solenza	2003	2005	93c46 8pin, 128 Bytes	-	-	Philips® fixed code PH00 (33)
Solenza	2003	2005	93c56 8pin, 256 Bytes	-	-	Philips® fixed code PH00 (33)
Super Nova	1999	2004	93c46 8pin, 128 Bytes	-	-	Philips® fixed code PH00 (33)
Super Nova	1999	2004	93c56 8pin, 256 Bytes	-	-	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>DAEWOO</b>						
Aranos	-	1997	Motorola MC68HC05B6 52pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Cielo	-	1997	Motorola MC68HC05B6 52pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Espero	-	1997	Motorola MC68HC05B6 52pin, 256 Bytes	DAE46TK1/DAE46STK1	-	Megamos® fixed code MG00 (13)
Lacetti	2002	2005	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Lanos	1997	2002	Motorola MC68HC05B6 52pin, 256 Bytes	DAE47SU/DAE47STK1	TK100	Megamos® fixed code MG00 (13)
Leganza	1997	2000	Motorola MC68HC05B6 52pin, 256 Bytes	DAE47U/DAE47TK1	TK100	Megamos® fixed code MG00 (13)
Leganza	2001	2002	93c56 8pin, 256 Bytes	DAE47SU/DAE47STK1	TKM	Megamos® Crypto MG10 (48)
Matiz	1998	2000	Motorola MC68HC05B6 52pin, 256 Bytes	DAE47SP	-	Megamos® fixed code MG00 (13)
Nexia	1995	1997	Motorola MC68HC05B6 52pin, 256 Bytes	DAE46TK1	-	Megamos® fixed code MG00 (13)
Nubira	1997	2000	Motorola MC68HC05B6 52pin, 256 Bytes	DAE48SU/DAE48STK1	TK100	Megamos® fixed code MG00 (13)
Nubira	2000	2002	93c56 8pin, 256 Bytes	DAE48U/DAE48TK1	TKM	Megamos® Crypto MG10 (48)
Tacuma	2000	2006	93c56 8pin, 256 Bytes	DAE48SU/DAE48STK1	TKM	Megamos® Crypto MG10 (48)
Windstorm	2006	2010	95040, 8pin, 512 Bytes	-	-	Philips® Crypto PH20 (46)
<b>DAIHATSU</b>						
Charade	1998	2004	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Cuore	1998	2006	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Domino	1999	2004	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Handivan	1999	2004	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Move	1997	2002	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Sirion	1998	2004	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Storia	1999	2004	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Terios	1997	2005	93c66 8pin, 512 Bytes	DAI1SU/DAI1STK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Various	1998	1999	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Various	1998	2000	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
<b>DODGE</b>						
Caravan	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Caravan	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Caravan	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Dakota	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Dakota	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Dakota	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Durango	2001	2003	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Durango	2001	2003	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Durango	2001	2003	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Intrepid	1999	2004	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Intrepid	1999	2004	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Intrepid	1999	2004	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Neon	2001	2007	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Neon	2001	2007	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Neon	2001	2007	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Ram	2002	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Ram	2002	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Ram	2002	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Stratus Coupe	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Stratus Coupe	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Stratus Coupe	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>DODGE</b>						
Stratus Sedan	2001	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas <sup>®</sup> Crypto TC04-64 (4D-64)
Stratus Sedan	2001	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas <sup>®</sup> Crypto TC04-64 (4D-64)
Stratus Sedan	2001	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas <sup>®</sup> Crypto TC04-64 (4D-64)
<b>DUCATI</b>						
600	1997	-	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
600	1997	-	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
620	2006	-	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
620	2006	-	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
749	2003	2006	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
749	2003	2006	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
800	2003	2006	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
800	2003	2006	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
900	1999	-	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
900	1999	-	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
999	2003	2006	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
999	2003	2006	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
1000	2006	-	24c02 8pin, 256 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
1000	2006	-	24c16 8pin, 2048 Bytes	-	-	Temic <sup>®</sup> fixed code TM10 (11)
<b>FERRARI</b>						
612 Scaglietti	2004	2011	Motorola MC68HC912DG128 112pin, 2048 Bytes)	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
612 Scaglietti	2004	2011	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
<b>FIAT</b>						
500	2007	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips <sup>®</sup> Crypto PH20 (46)
Albea	2002	2006	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Albea	2002	2006	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Barchetta	1995	2002	93c46 8pin, 128 Bytes	FT1505TK5	-	Megamos <sup>®</sup> fixed code MG00 (13)
Brava	-	-	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505TK	TK100/GK100/CK100	Temic <sup>®</sup> fixed code TM10 (11)
Brava	1995	1997	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos <sup>®</sup> fixed code MG00 (13)
Bravo	1995	1997	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos <sup>®</sup> fixed code MG00 (13)
Bravo	1997	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic <sup>®</sup> fixed code TM10 (11)
Bravo	1997	2001	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic <sup>®</sup> fixed code TM10 (11)
Bravo	2007	-	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Bravo	2007	-	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Bravo	2009	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips <sup>®</sup> Crypto PH20 (46)
Cinquecento	1995	1998	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos <sup>®</sup> fixed code MG00 (13)
Coupe	1995	2000	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/TK5	Philips <sup>®</sup> fixed code PH00 (33)
Croma	1995	1997	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/TK5	Philips <sup>®</sup> fixed code PH00 (33)
Doblò	2000	2005	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Doblò	2000	2005	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Doblò	2000	2007	93c66 8pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Doblò	2006	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips <sup>®</sup> Crypto PH20 (46)
Ducato	1996	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/GKM	Megamos <sup>®</sup> fixed code MG00 (13)
Ducato	2006	2011	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Ducato	2006	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos <sup>®</sup> Crypto MG10 (48)
Ducato	2010	2010	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips <sup>®</sup> Crypto PH20 (46)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>FIAT</b>						
Fiorino	2007	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Grande Punto	2005	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Idea	2003	2009	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Linea	2007	-	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Linea	2007	-	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Marea	-	-	93c46 8pin, 128 Bytes	FT1505U/FT1505TK	TK100/GKM	Megamos® fixed code MG00 (13)
Marea	1996	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Marea	1996	2002	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Marengo	1996	2001	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Multipla	1996	1998	93c46 8pin, 128 Bytes	FT1505U/FT1505TK	TK100/GKM	Megamos® fixed code MG00 (13)
Multipla	1998	2010	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TKM/GKM	Megamos® Crypto MG10 (48)
Palio	1996	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Palio	1996	2001	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT1505U/FT1505CTK	TK100/TK5	Temic® fixed code TM10 (11)
Palio	1999	-	93c66 8pin, 512 Bytes	FT1505U/FT1505TK	TKM/GKM	Megamos® Crypto MG10 (48)
Palio	2002	-	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Palio	2002	-	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Panda	1995	2002	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/GKM	Megamos® fixed code MG00 (13)
Panda	2002	2009	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Panda	2002	2009	Motorola MC9S12DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Panda	2002	2009	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Punto	1995	1999	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Punto	1999	2005	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	1999	2005	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	2001	2007	93c66 8pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	2005	-	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	2005	-	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	-	2005	95320 8pin, 4096 Bytes	FT50U/FT50TK	TKM/GKM	Megamos® Crypto MG10 (48)
Punto	-	2005	95160, 8pin, 2048 Bytes	FT50U/FT50TK	TKM/GKM	Megamos® Crypto MG10 (48)
Scudo	1996	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Scudo	1996	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Scudo	1997	1999	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Seicento	1997	2000	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Siena	-	-	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Siena	2001	2007	93c66 8pin, 512 Bytes	FT50U/FT50TK	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	-	2007	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	-	2007	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	2000	2005	93c66 8pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	2001	2008	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	2001	2008	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	2007	-	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Stilo	2007	-	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Strada	1999	2007	93c66 8pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Strada	2001	2007	93c66 8pin, 512 Bytes	-	-	Megamos® Crypto MG10 (48)
Tempra	1995	1996	93c46 8pin, 128 Bytes	FT1505U/FT1505CTK	TK100/GKM	Megamos® fixed code MG00 (13)
Ulysse	1996	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ulysse	1996	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ulysse	1996	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>FORD</b>						
Courier	1998	2002	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Escape	1998	2002	95040, 8pin, 512 Bytes	FD21U/FD21TK/FD21-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Escort	1995	2000	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Expedition	1997	2003	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Explorer	1995	2000	95040, 8pin, 512 Bytes	FD21U/FD21TK/FD21-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Explorer	1997	1999	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Fiesta	2002	2010	93c56 8pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
Fiesta	2002	2010	93c86(28000766), 8pin, 2048 Bytes	-	-	Texas® Crypto TPXX (4D)
Focus	1997	2003	95040, 8pin, 512 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Focus	2004	2010	93c86(28000766), 8pin, 2048 Bytes	FD40U/FD40BTK/FD40-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Fusion	2002	2008	93c86(28000766), 8pin, 2048 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Galaxy	1997	1999	TMS370C702, 28pin, 256 Bytes	-	-	Philips® Crypto PH1C (42)
Ka	1997	2002	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Mondeo	1995	2000	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Mondeo	2002	2010	95040, 8pin, 512 Bytes	FD40U/FD40BTK/FD40-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Mustang	1996	2004	TMS370C702, 28pin, 256 Bytes	FD21U/FD21BTK/FD21-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Probe	2002	2010	Motorola MC68HC705P3, 28pin, 128 Bytes	-	-	Temic® fixed code TM20 (12)
Puma	1998	2001	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Ranger	2007	-	93c86(28000766), 8pin, 2048 Bytes	-	-	Texas® Crypto TPXX (4D)
Scorpio	1995	1998	TMS370C702, 28pin, 256 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Taurus	-	2000	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Taurus	2004	2010	95040, 8pin, 512 Bytes	FD21U/FD21TK/FD21-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Transit	1995	2000	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Transit	1997	2002	95040, 8pin, 512 Bytes	FD3U/FD3TK/FD3-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Windstar	1999	2000	TMS370C702, 28pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
<b>HOLDEN</b>						
Commodore	2013	2017	95320 8pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Monterey	1998	2005	93c66 8pin, 512 Bytes	-	-	Texas® Crypto TPXX (4D)
Jackaroo	1999	2005	93c66 8pin, 512 Bytes	TR47SU/TR47STK/TR47-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
<b>HONDA</b>						
Accord	1995	1999	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
Civic	1995	2001	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Civic	1995	2001	Motorola MC68HC05B6 52pin, 256 Bytes	HD90U/HD90TK	TK100/TK5	Philips® fixed code PH00 (33)
Civic	2006	2011	24c04 8pin, 512 Bytes	HD1U/HD1BTK/HD1-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
CR-V	1997	1999	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Integra	1998	2001	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Legend	1996	2004	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Odyssey	2005	-	24c02 8pin, 256 Bytes	HD1U/HD1BTK/HD1-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Passport	1998	2002	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Prelude	1997	2002	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Shuttle	1995	2000	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
<b>HONDA MOTORBIKE</b>						
CBR 1000	2004	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
CBR 1100 F	1999	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
CBR 600 RR	2003	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>HONDA MOTORBIKE</b>						
CBR 600F	1999	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
CBR 900	2003	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Gold 2800	2001	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
NT 650 V	1999	-	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Shadow 750	2002	2004	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Silverwing	2000	2001	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
VT 750 C4	2000	2004	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
VTX 1800	2000	2002	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
X11	2000	2001	93c56 8pin, 256 Bytes	HD70U/HD70TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>HYUNDAI</b>						
Accent	-	2004	95320 8pin, 4096 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Accent	1996	1999	93c56 8pin, 256 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Accent	2004	-	95160, 8pin, 2048 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Atos	1997	2000	93c56 8pin, 256 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Atos Prime	2003	-	95160, 8pin, 2048 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Coupe	1996	-	93c56 8pin, 256 Bytes	HY6U/HY6TK/HY6-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Elantra	2004	-	95160, 8pin, 2048 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Era	2008	-	95160, 8pin, 2048 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Galloper	1999	2003	93c56 8pin, 256 Bytes	HY10U/HY10TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Getz	2007	-	95160, 8pin, 2048 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
H-1	1998	2001	93c56 8pin, 256 Bytes	HY6U/HY6TK/HY6-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
H200	-	-	93c56 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
i10	2010	-	95160, 8pin, 2048 Bytes	HY14U/HY14TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
i30	2010	-	95160, 8pin, 2048 Bytes	TR49U/TR49TK/TR49-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Lantra	1996	2000	93c56 8pin, 256 Bytes	HY6U/HY6TK/HY6-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Santa Fe	2009	-	95320 8pin, 4096 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Sonata	2008	-	95160, 8pin, 2048 Bytes	HY14SU/HY14STK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>ISUZU</b>						
Dmax	2010	-	93c66 8pin, 512 Bytes	TR47SU/TR47STK/TR47-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>IVECO</b>						
Daily	1998	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/TK5	Philips® fixed code PH00 (33)
Daily	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Daily	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Daily	2012	2015	95640	-	-	Philips® Crypto PH20 (46)
Eurocargo	2007	-	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Eurocargo	2007	-	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
<b>JAGUAR</b>						
Sovereign	-	-	93c46 8pin, 128 Bytes	JA1U	TK100/GKM	Megamos® fixed code MG00 (13)
XJ	-	-	93c46 8pin, 128 Bytes	JA1U	TK100/GKM	Megamos® fixed code MG00 (13)
XJ6	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
XJS	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
XK	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)
XK8	1994	1997	93c46 8pin, 128 Bytes	-	-	Megamos® fixed code MG00 (13)



MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>JEEP</b>						
Cherokee	1999	2001	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Cherokee	1999	2001	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Cherokee	1999	2001	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
CJ5	1999	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
CJ5	1999	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
CJ5	1999	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
CJ7	1999	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
CJ7	1999	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
CJ7	1999	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Grand Cherokee	1999	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Grand Cherokee	1999	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Grand Cherokee	1999	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Liberty	2002	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Liberty	2002	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Liberty	2002	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Patriot	2007	-	24c16 8pin, 2048 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Wrangler	1998	2005	24c02 8pin, 256 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Wrangler	1998	2005	Motorola MC68HC08AB16A, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Wrangler	1998	2005	Motorola MC68HC08AZ32, 64pin, 512 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Texas® Crypto TC04-64 (4D-64)
Wrangler	2007	-	24c16 8pin, 2048 Bytes	Y160U/Y159TK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>KIA</b>						
Cee'd	2005	2008	95160, 8pin, 2048 Bytes	KI22U	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Cerato	2003	-	95160, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Rio	2001	2005	93c46 8pin, 128 Bytes	KI3SU/KI3STK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Sephia	1999	2004	93c46 8pin, 128 Bytes	KI3SU/KI3STK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Spectra	2005	-	95160, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Sportage	2001	2003	93c46 8pin, 128 Bytes	KI3SU/KI3STK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
<b>LANCIA</b>						
Dedra	1995	1999	93c46 8pin, 128 Bytes	LA1505TK5	-	Megamos® fixed code MG00 (13)
Dedra	1997	1999	Motorola MC68HC05E6, 28pin, 160 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Dedra	1997	1999	Motorola MC68HC08AZ32, 64pin, 512 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Delta	1995	1999	93c46 8pin, 128 Bytes	LA1505TK5	-	Megamos® fixed code MG00 (13)
Delta	2010	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
K	1995	2001	93c46 8pin, 128 Bytes	AR20U	TK100	Philips® fixed code PH00 (33)
K Coupe	1997	2001	93c46 8pin, 128 Bytes	AR20U	TK100	Philips® fixed code PH00 (33)
Lybra	1999	2006	Motorola MC68HC08AZ32, 64pin, 512 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Musa	2010	2011	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Thesis	2002	2009	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Thesis	2002	2009	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Ypsilon	1996	2003	Motorola MC68HC05E6, 28pin, 160 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Ypsilon	1996	2003	Motorola MC68HC08AZ32, 64pin, 512 Bytes	LA1505TK5	-	Temic® fixed code TM10 (11)
Ypsilon	2007	-	95320 8pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Ypsilon	2007	-	95160, 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Zeta	1996	2002	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Zeta	1996	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Zeta	1996	2002	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>LEXUS</b>						
ES300	1999	2003	93c56 8pin, 256 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
GS300	1998	2003	93c56 8pin, 256 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
IS200	-	-	93c56 8pin, 256 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
RX300	1998	2003	93c56 8pin, 256 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
<b>MASERATI</b>						
Granturismo	2007	-	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Granturismo	2007	-	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Quattroporte	2004	2012	Motorola MC68HC912DG128 112pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Quattroporte	2004	2012	MC9S12DP256 112pin, 4096 Bytes	FT22U/FT22TK/FT22-KF	TKM/GKM	Megamos® Crypto MG10 (48)
<b>MAZDA</b>						
2	2002	2010	93c56 8pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
2	2002	2010	93c86(28000766), 8pin, 2048 Bytes	-	-	Texas® Crypto TPXX (4D)
323	1995	1999	Motorola MC68HC705P3, 28pin, 128 Bytes	MZ23TK5	-	Temic® fixed code TM20 (12)
626	1995	1999	Motorola MC68HC705P3, 28pin, 128 Bytes	MZ27TK5	-	Temic® fixed code TM20 (12)
MX-3	1995	1998	Motorola MC68HC705P3, 28pin, 128 Bytes	MZ23TK5	-	Temic® fixed code TM20 (12)
MX-5	1995	1998	Motorola MC68HC705P3, 28pin, 128 Bytes	MZ23TK5	-	Temic® fixed code TM20 (12)
MX-6	1995	1997	Motorola MC68HC705P3, 28pin, 128 Bytes	MZ27TK5	-	Temic® fixed code TM20 (12)
Xedos 6	1995	1999	Motorola MC68HC705P3, 28pin, 128 Bytes	MZ27TK5	-	Temic® fixed code TM20 (12)
Xedos 9	1995	2002	Motorola MC68HC705P3, 28pin, 128 Bytes	-	-	Temic® fixed code TM20 (12)
<b>MERCEDES</b>						
Actros	1998	2006	93c56 8pin, 256 Bytes	YS15TK1	-	Megamos® fixed code MG00 (13)
Actros	1998	2006	93c66 8pin, 512 Bytes	YS15TK1	-	Megamos® fixed code MG00 (13)
Actros	1998	2006	93c86(28000766), 8pin, 2048 Bytes	YS15TK1	-	Megamos® fixed code MG00 (13)
Atego	1998	2006	93c56 8pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Atego	1998	2006	93c66 8pin, 512 Bytes	-	-	Megamos® fixed code MG00 (13)
Atego	1998	2006	93c86(28000766), 8pin, 2048 Bytes	-	-	Megamos® fixed code MG00 (13)
Axor	1998	2006	93c56 8pin, 256 Bytes	-	-	Megamos® fixed code MG00 (13)
Axor	1998	2006	93c66 8pin, 512 Bytes	-	-	Megamos® fixed code MG00 (13)
Axor	1998	2006	93c86(28000766), 8pin, 2048 Bytes	-	-	Megamos® fixed code MG00 (13)
<b>MINI</b>						
<b>MINI</b>						
<b>MITSUBISHI</b>						
3000 GT	1996	2001	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
ASX	2010	2011	24c01, 8pin, 128 Bytes	MT8SU/MT8TK/MT8S-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Carisma	1996	2000	93c46 8pin, 128 Bytes	VL15TK1	-	Philips® fixed code PH00 (33)
Carisma	2000	2004	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
Chariot	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Colt	1996	2000	24c01, 8pin, 128 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Eagle Vista Wagon	1996	-	24c01, 8pin, 128 Bytes	MT1BTK3	-	Texas® fixed code TX00 (4C)
Eclipse	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Expo	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Express	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Galant	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Grandis	2006	-	24c02 8pin, 256 Bytes	MT8SU/MT8TK/MT8S-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
L200	-	2009	24c02 8pin, 256 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
L200	2006	-	24c02 8pin, 256 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>MITSUBISHI</b>						
L200	2010	2015	25320	-	-	Philips® Crypto PH20 (46)
Lancer	1996	2003	24c01, 8pin, 128 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Lancer	2008	2010	24c16 8pin, 2048 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Magna	1996	1999	93c46 8pin, 128 Bytes	-	-	Philips® fixed code PH00 (33)
Mirage	1996	2000	24c01, 8pin, 128 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Montero	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Montero	2007	-	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
Nativa	2008	-	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
Nimbus	1998	1999	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Outlander	2006	-	24c02 8pin, 256 Bytes	MT8SU/MT8SBTK	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Pajero	1996	2000	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Pajero Sport	2007	-	24c02 8pin, 256 Bytes	-	-	Philips® Crypto PH20 (46)
Shogun	1996	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Space Gear	1996	-	24c01, 8pin, 128 Bytes	MT1BTK3	-	Texas® fixed code TX00 (4C)
Space Runner	1998	1999	24c01, 8pin, 128 Bytes	MT1U/MT1BTK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Space Star	1996	1999	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Space Star	1999	2005	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
Space Wagon	1996	-	24c01, 8pin, 128 Bytes	MT1BTK3	-	Texas® fixed code TX00 (4C)
<b>NISSAN</b>						
Almera	2000	2003	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Almera Tino	2000	2003	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Altima	2001	2004	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Atleon	2002	-	TMS370C702, 28pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
Cabstar	2000	-	TMS370C702, 28pin, 256 Bytes	NS27U/NS27TK/NS2TK13	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Cefiro	2000	2003	TMS370C702, 28pin, 256 Bytes	-	-	Texas® Crypto TPXX (4D)
Interstar	1998	2001	Motorola MC68HC05B6 52pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Interstar	2002	2010	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Maxima	1995	1999	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Micra	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Micra	2000	2003	TMS370C702, 28pin, 256 Bytes	NS27U/NS27TK/NS2TK13	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Murano	2003	2007	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Navara	2003	2005	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Pathfinder	1999	2004	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Patrol	2004	-	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Primastar	2006	2013	95080, 8pin, 2048 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Primera	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Primera	1999	2002	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Pulsar	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Pulsar	1998	2000	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Sentra	2000	2006	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Serena	1996	1999	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Sunny	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Terrano II	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Terrano II	2002	2006	TMS370C702, 28pin, 256 Bytes	NS27U/NS27TK/NS2TK13	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Vanette	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Vanette	2000	-	TMS370C702, 28pin, 256 Bytes	NS27U/NS27TK/NS2TK13	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
X-Trail	2001	2003	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>NISSAN</b>						
Xterra	2000	2004	TMS370C702, 28pin, 256 Bytes	NS34U/NS34BTK/NS34-KF	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
<b>OPEL/VAUXHALL</b>						
Antara	2006	2010	95040, 8pin, 512 Bytes	OPL1U	TK100	Philips® Crypto PH20 (46)
Astra	2009	-	24c16 8pin, 2048 Bytes	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Frontera	1996	1999	93c46 8pin, 128 Bytes	HD90U/HD90TK	TK100/GKM	Megamos® fixed code MG00 (13)
Frontera	1999	2003	93c46 8pin, 128 Bytes	HD90U/HD90TK	TKM/GKM	Megamos® Crypto MG10 (48)
Insignia	2008	-	24c16 8pin, 2048 Bytes	VX5U/VX5BTK/VX5-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Monterey	1998	2005	93c66 8pin, 512 Bytes	-	-	Texas® Crypto TPXX (4D)
Movano	1998	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Movano	1998	2001	93c56 8pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Movano	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Movano	2007	-	95080, 8pin, 2048 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Vivaro	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Vivaro	2007	-	95080, 8pin, 2048 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>PEUGEOT</b>						
106	1997	2004	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	-	Motorola MC68HC05E6, 28pin, 160 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	1999	95040, 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	1999	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
306	1997	2002	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
406	1997	1999	93c46 8pin, 128 Bytes	PG31U/PG31TK1	TK100	Philips® fixed code PH00 (33)
806	1998	2002	95040 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
806	1998	2002	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Bipper	2009	-	93c86(28000766), 8pin, 2048 Bytes	FT22U/FT22TK/FT22-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Boxer	-	2001	93c46 8pin, 128 Bytes	FT50U/FT50TK	TK100/GKM	Megamos® fixed code MG00 (13)
Boxer	2006	2011	95320 8pin, 4096 Bytes	-	-	Megamos® Crypto MG10 (48)
Boxer	2006	2011	95160, 8pin, 2048 Bytes	-	-	Megamos® Crypto MG10 (48)
Expert	1998	2006	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Expert	1998	2006	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Expert	1998	2006	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Partner	1998	2001	93c46 8pin, 128 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Partner	2008	-	93c86(28000766), 8pin, 2048 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Ranch	1998	2001	95040, 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ranch	1998	2001	93c66 8pin, 512 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
Ranch	1998	2001	Motorola MC68HC05E6, 28pin, 160 Bytes	CN22U/CN22TK	TK100/TK5	Philips® fixed code PH00 (33)
<b>PEUGEOT MOTORBIKE</b>						
Alise	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Alise	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Eliseo	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Eliseo	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Speedfight	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
Speedfight	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	-	-	Temic® fixed code TM10 (11)
<b>PIAGGIO</b>						
Beverly	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>PIAGGIO</b>						
Beverly	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Liberty	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Liberty	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Vespa	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
Vespa	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
X8	-	-	Motorola MC68HC05B16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
X8	-	-	Motorola MC68HC05X16, 64pin, 256 Bytes	FT22U/FT22TK/FT22-KF	TK100/TK5	Temic® fixed code TM10 (11)
<b>RENAULT</b>						
Clio	1995	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1995	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1995	2001	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1995	2001	93c56 8pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Clio	2001	2006	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Clio	2005	2012	95160, 8pin, 2048 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Clio Sport	2009	-	Motorola MC68HC912DG128 112pin, 2048 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Clio Sport	2009	-	MC9S12DP256 112pin, 4096 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Espace	1997	2002	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Espace	2003	-	95160 8pin, 2048 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kangoo	1998	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Kangoo	1998	2001	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Kangoo	2002	2007	93c66 8pin, 512 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kangoo	2002	2009	93c66 8pin, 512 Bytes	VE20U/VE20TK/VE20-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Kangoo	2007	-	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Laguna	1995	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Laguna	1995	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Laguna	2000	2007	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Laguna	2000	2007	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Mascott	1998	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Mascott	1998	2001	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Master	1998	2001	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Master	1998	2001	93c56 8pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Master	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Master	2007	-	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Mégane	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Mégane	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Mégane	2003	2008	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Mégane	2003	2008	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Modus	2004	2012	95160 8pin, 2048 Bytes	PG33U/PG33TK/PG33-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Safrane	1996	2000	93c46 8pin, 128 Bytes	RN30U/RN30TK/RN30-KF	TK100/TK5	Philips® fixed code PH00 (33)
Scenic	2003	2008	Motorola MC68HC912DG128 112pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Scenic	2003	2008	MC9S12DP256 112pin, 4096 Bytes	-	-	Philips® Crypto PH20 (46)
Symbol	1998	2003	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Symbol	1998	2003	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Thaila	1999	2003	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Thaila	1999	2003	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>RENAULT</b>						
Trafic	1997	2001	93c46 8pin, 128 Bytes	-	-	Philips® fixed code PH00 (33)
Trafic	1997	2001	93c56 8pin, 256 Bytes	-	-	Philips® fixed code PH00 (33)
Trafic	2002	2007	93c66 8pin, 512 Bytes	RN30U/RN30TK/RN30-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Trafic	2007	-	95080, 8pin, 2048 Bytes	-	-	Philips® Crypto PH20 (46)
Twingo	1996	2001	Motorola MC68HC05B16, 64pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Twingo	1996	2001	Motorola MC68HC05B6 52pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Twingo	1998	2001	93c46 8pin, 128 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Twingo	1998	2001	93c56 8pin, 256 Bytes	VE20U/VE20TK/VE20-KF	TK100/TK5	Philips® fixed code PH00 (33)
Twingo	2002	2007	93c66 8pin, 512 Bytes	VE20U/VE20TK/VE20-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
<b>ROVER</b>						
600	1998	2003	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
618	1996	1999	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
620	1996	1999	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
800	1997	1998	Motorola MC68HC05B6 52pin, 256 Bytes	RV3U/RV3TK1	TK100	Philips® fixed code PH00 (33)
<b>SEAT</b>						
Alhambra	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Alhambra	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Alhambra	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Arosa	1997	1999	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Arosa	1997	1999	Motorola MC68HC05B6 52pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Arosa	1997	2000	TMS370C702, 28pin, 256 Bytes	-	-	Philips® Crypto PH1C (42)
Cordoba	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Cordoba	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Cordoba	1999	2002	TMS370C702, 28pin, 256 Bytes	-	-	Philips® Crypto PH1C (42)
Ibiza	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Ibiza	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Ibiza	1998	2000	TMS370C702, 28pin, 256 Bytes	-	-	Philips® Crypto PH1C (42)
Inca	1996	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Inca	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Inca	1998	2000	TMS370C702, 28pin, 256 Bytes	-	-	Philips® Crypto PH1C (42)
Leon	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Toledo	1995	1999	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Toledo	1995	1999	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Toledo	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
<b>ŠKODA</b>						
Fabia	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Felicia	1996	2001	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Felicia	1996	2001	Motorola MC68HC05B6 52pin, 256 Bytes	SK21STK1	-	Philips® fixed code PH00 (33)
Octavia	2009	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Pick-up	1996	-	Motorola MC68HC05B16, 64pin, 256 Bytes	SK21SAP	-	Philips® fixed code PH00 (33)
Pick-up	1996	-	Motorola MC68HC05B6 52pin, 256 Bytes	SK21SAP	-	Philips® fixed code PH00 (33)
Rapid	2012	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Superb	2008	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Yeti	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>SUBARU</b>						
Bighorn	1999	2005	93c66 8pin, 512 Bytes	SUB2U/SUB2TK	TK100/GK100/CK100	Texas® Crypto TPXX (4D)
Impreza	1996	2000	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Legacy	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
Outback	1996	1998	Motorola MC68HC05B6 52pin, 256 Bytes	NS27U/NS27TK	TK100/TK5	Philips® fixed code PH00 (33)
<b>SUZUKI</b>						
Alto	1996	2002	24c01, 8pin, 128 Bytes	SU15U/SU15TK/SU15-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Baleno	1996	-	93c66 8pin, 512 Bytes	SU15U/SU15TK/SU15-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Baleno	1996	-	93c66 8pin, 512 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Baleno	1996	2001	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Carry	1999	2005	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Grand Vitara	1996	2002	24c01, 8pin, 128 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Jimny	1999	2002	24c01, 8pin, 128 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Super Carry	1999	2000	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Swift	1996	2005	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Swift	1996	2005	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Vitara	1996	2002	24c01, 8pin, 128 Bytes	-	-	Texas® fixed code TX00 (4C)
Wagon R	1998	2000	24c01, 8pin, 128 Bytes	SU17U/SU17TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
<b>TOYOTA</b>						
Avalon	1996	2005	25020 8pin, 512 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Avensis	1996	2003	93c56 8pin, 256 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Avensis	1998	2000	Motorola MC68HC05E6, 28pin, 160 Bytes	TR56U/TR56TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Camry	-	2004	93c66 8pin, 512 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Camry	1996	2005	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Camry	1996	2005	95080, 8pin, 2048 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Camry	1996	2005	93c56 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Carina	-	1999	Motorola MC68HC05E6, 28pin, 160 Bytes	TR56U/TR56TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Celica	1999	2005	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	24c02 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	25020 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	95080, 8pin, 2048 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Corolla	1996	2006	93c56 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Crown Majesta	1999	2005	95080, 8pin, 2048 Bytes	TR48U/TR48TK/TR48-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Crown Majesta	1999	2005	95080, 8pin, 2048 Bytes	TR53U/TR53-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Hiace	1995	2006	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	24c02 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	25020 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	25080 8pin, 1024 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1995	2006	95080, 8pin, 2048 Bytes	-	-	Texas® fixed code TX00 (4C)
Hiace	1996	2005	93c56 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Highlander	1996	2004	24c02 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Land Cruiser	-	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Land Cruiser	1999	2004	93c56 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
MR2	1999	2004	93c66 8pin, 512 Bytes	TR41TK/TR41U	TK100/GK100/CK100	Texas® fixed code TX00 (4C)

MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>TOYOTA</b>						
Picnic	-	1999	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Prius	-	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	25080 8pin, 1024 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	95080, 8pin, 2048 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Rav 4	1996	2004	93c56 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Sequoia	-	2004	93c66 8pin, 512 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Solara	1999	2004	24c02 8pin, 256 Bytes	TR47U/TR47TK/TR47-KF	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Various	1996	2006	93c66 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Various	1996	2006	24c02 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Various	1996	2006	25020 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1996	2005	93c56 8pin, 256 Bytes	TR56U/TR56TK	TK100/GK100/CK100	Texas® fixed code TX00 (4C)
Yaris	1999	2005	24c02 8pin, 256 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	25020 8pin, 512 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	25080 8pin, 1024 Bytes	-	-	Texas® fixed code TX00 (4C)
Yaris	1999	2005	95080, 8pin, 2048 Bytes	-	-	Texas® fixed code TX00 (4C)
<b>VOLKSWAGEN</b>						
Amarok	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Bora	2009	2012	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Caddy	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Caddy	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Caddy	1998	2000	TMS370C702, 28pin, 256 Bytes	V66U/V66TK/V66-KF	TK50/CK50	Philips® Crypto PH1C (42)
Caddy	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Cross fox	2003	-	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Eos	2009	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Fox	2003	-	93c56 8pin, 256 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Gol	2008	-	93c56 8pin, 256 Bytes	V70U/V70TK	TKM/GKM	Megamos® Crypto MG10 (48)
Golf	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Golf	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Golf 6	2009	2012	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Golf Cabrio	1998	2000	TMS370C702, 28pin, 256 Bytes	V66U/V66TK/V66-KF	TK50/CK50	Philips® Crypto PH1C (42)
Jetta	2009	2012	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Lupo	1998	2000	TMS370C702, 28pin, 256 Bytes	V66U/V66TK/V66-KF	TK50/CK50	Philips® Crypto PH1C (42)
Parati	2008	-	93c56 8pin, 256 Bytes	V70U/V70TK	TKM/GKM	Megamos® Crypto MG10 (48)
Passat	1994	1997	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Passat	1994	1997	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Passat USA	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Pointer	2004	-	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Polo	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Polo	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Polo	1998	2000	TMS370C702, 28pin, 256 Bytes	V66U/V66TK/V66-KF	TK50/CK50	Philips® Crypto PH1C (42)
Polo	2009	2012	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Santana	2007	-	93c56 8pin, 256 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Saveiro	2008	-	93c56 8pin, 256 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Scirocco	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Sharan	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)
Sharan	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V66U/V66TK/V66-KF	TK100/TK5	Philips® fixed code PH00 (33)



MAKE - MODEL	FROM	TO	EEPROM	KEYLINE REFERENCE	KEYLINE TRANSPONDER	TRANSPONDER TYPE
<b>VOLKSWAGEN</b>						
Spacefox	2003	-	93c56 8pin, 256 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
SportVan	2003	-	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Suran	2003	-	93c56 8pin, 256 Bytes	-	-	Megamos® Crypto MG10 (48)
Tiguan	2010	-	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Touareg	-	2008	93c86(28000766), 8pin, 2048 Bytes	V66U/V66TK/V66-KF	TK100/GK100/CK100	Philips® Crypto PH20 (46)
Touran 2	2011	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Transporter	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Transporter	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Transporter	2003	2009	93c86(28000766), 8pin, 2048 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Transporter T4	1998	2000	TMS370C702, 28pin, 256 Bytes	V35U/V35TK10	TK50	Philips® Crypto PH1C (42)
Transporter T5	2003	2009	93c86(28000766), 8pin, 2048 Bytes	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Transporter T6	2010	2013	SuperVAG	V66U/V66TK/V66-KF	TKM/GKM	Megamos® Crypto MG10 (48)
Vento	1995	1998	Motorola MC68HC05B16, 64pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
Vento	1995	1998	Motorola MC68HC05B6 52pin, 256 Bytes	V35U/V35TK1	TK100	Philips® fixed code PH00 (33)
<b>VOLVO</b>						
850	1996	1997	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
940	1996	1998	93c46 8pin, 128 Bytes	VL10TK1	-	Philips® fixed code PH00 (33)
960	1996	1998	93c46 8pin, 128 Bytes	VL10TK1	-	Philips® fixed code PH00 (33)
C70	1997	1998	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
C70	1998	-	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
Polar	1996	-	93c46 8pin, 128 Bytes	VL10TK1	-	Philips® fixed code PH00 (33)
S40	1996	1998	93c46 8pin, 128 Bytes	VL15TK1	-	Philips® fixed code PH00 (33)
S40	1998	2004	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
S70	1997	1998	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
S70	1998	-	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
S80	1998	1999	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
V40	1996	1998	93c46 8pin, 128 Bytes	VL15TK1	-	Philips® fixed code PH00 (33)
V40	1996	1998	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)
V40	1996	1998	93c66 8pin, 512 Bytes	-	-	Philips® Crypto PH10 (44)
V70	1997	1998	93c46 8pin, 128 Bytes	VL17U/VL17TK1	TK100	Philips® fixed code PH00 (33)
V70	1998	2000	93c56 8pin, 256 Bytes	-	-	Philips® Crypto PH10 (44)

All the brands and trade marks mentioned here are the exclusive property of the respective car manufacturers or groups.  
The list of vehicles mentioned above can be integrated with new car models and is subject to updating.  
All the information in this guide are for guidance only.